

13 JAN 1965

OUT 4335

Mult

P 122101Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NE B
 RUCVAA/4080 STRAT WG CL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEAHQ/DIA WASHDC
 RUECYH/NAVREC ONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 3651.

1965 JAN 12 21 23

COPIES RECEIVED 7			
CyNo.	Office	Act.	Rec'd
1	Master File		
2	OS		
	ADMIN		
	SEC BR		
	P&DS		
	CSD		
	IPD		
	PD		
	PSD		
3	TID	✓	
	PAG		
	CIA/PID		
	DIAXX-4		
	SPAD		
	DIAAP		
	Destroyed		

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).


1. CAMERA B 15 WAS EMPLOYED IN MISSION 3982 FLOWN ON 8 JANUARY 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: ROLLER CHATTER IS PRESENT ALONG THE INBOARD SIDE THROUGHOUT. A PERSISTENT PLUS DENSITY LINE OF VARYING INTENSITY WAS NOTED PARALLEL TO AND 3.25" FROM THE INBOARD EDGE. ANOTHER PLUS DENSITY LINE APPEARS INTERMITTENTLY 4.45" FROM THE INBOARD EDGE. A ROW OF SMALL DIGS SPACED 6.3" APART IS FOUND PARALLEL TO AND 1.3" FROM THE INBOARD EDGE ON FRAMES 1 TO THE HEAT SPLICE ON FRAME 261. RANDOM PLUS DENSITY STREAKS ARE COMMON WITHIN ROUGHLY 2.0" OF THE OUTBOARD EDGE BETWEEN FRAMES 1560 THROUGH 1606 AND INFREQUENTLY DURING THE REST OF THE MISSION. A SERIES OF CLUSTERS OF SMALL EMULSION LIFTS RECUR EVERY 8.0" OR MULTIPLES THEREOF 2.25" FROM THE INBOARD EDGE STARTING WITH FRAME 2161 AND DECREASING WITH SIZE AND FREQUENCY TO FRAME 2198. HEAT SPLICES ARE LOCATED IN FRAMES 261 AND 1537. A MANUFACTURER'S SPLICE IS

SECRET



-2-

PRESENT ON FRAME 2415.

C. 9L SIDE: THE OUTBOARD EDGE CONTAINS MINOR STATIC DISCHARGES. A SMALL FLARE IS PRESENT ON THE INBOARD EDGE, 1.75" FROM THE DATA CHAMBER. THE METERING IS ONLY SLIGHTLY IRREGULAR, EXCEPT BETWEEN FRAMES 001 AND 002, WHICH ARE OVERLAPPED, AND BETWEEN FRAMES 2157/2158, 2159/2160, WHERE THE METERING RANGES FROM 0.08" - 1.15". PINHOLES ARE PRESENT INTERMITTENTLY THROUGHOUT THE FILM. MANUFACTURER'S SPLICES ARE POSITIONED WITHIN THE FORMATS OF FRAMES 047, 467, AND 1694. FRAMES 179 AND 1497 CONTAIN HEAT SPLICES.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0001 TO 2817.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FAULTS.

3. DUPLICATE POSITIVE:

A. THE PI SUITABILITY IS GOOD IN CLOUD FREE AREAS.

B. PRINTING AND PROCESSING ARE GOOD.

C. THE AVERAGE COVER IS APPROXIMATELY 20 PERCENT.

GP-1

S E C R E T

--END OF MESSAGE--